



6 important rules for experiments at PF

1. Remember phone numbers of UNTEN TOBAN (floor manager) 4209 and emergency call 3399.

2. Check the Emergency Exits, Emergency Assembly Areas and Fire Extinguishers around you.


3. Input the contact information of a member who is currently responsible in your experiments on the PF Experiment Information Management System <http://pf-userexp.kek.jp/> and the printed "Declaration of introduction of samples/chemicals into the Photon Factory" that has been sent as an attached PDF file to the spokesperson should be posted on the Beamline Display Board, which is located downstream of each beamline.

4. Follow the instructions by station master or UNTEN TOBAN to use electric devices, gas cylinders, circulating water for cooling etc.

5. Be careful to manage toxic materials and never waste them to environments.

6. Operate the Beamline Interlock System soundly but do not hesitate DUMP button if necessary.

Please submit "Beamtime Report" at the end of your experiments on the internet.
http://pfwww.kek.jp/appforms/beam_time_report.html



In case of emergency

BL-3A	"Declaration of introduction of samples/chemicals into the Photon Factory"
Baking 10/6 12:00	
BL-3B	
Toxic Gas CO	
BL-3C 1/2/3	

Beamline Display Board

Please refer to Safety Guide for PF Users for any inquiry.
<http://www2.kek.jp/imss/pf/eng/use/safety/>

