


2008/09/18 11:00 1.772x10¹³ ppp : 210kW @ 25Hz Operation. , Loss:~3%



DCCT Signal



3NBT Current Monitor Signal



3NBT Beam Bunch Signal